



POS	MISURA	
A	MM	518
B	MM	1300
C	MM	1170
D	MM	910
E	MM	1855
F		0°/-15°
G	MM	765
H	MM	550
I		0°/90°
J		-5°/90°